

Wolfgang Moroder Via Rezia, 64 Ortisei BZ 39046 Italy 137 Harley Street, London W1G 6BG Tel: +44 20 7034 3070 Fax: +44 20 7034 3071 Email: fmfcertification@fetalmedicine.com

Aug 24, 2015

FMF ID: 17976

Measurement of uterine artery PI

Dear Wolfgang Moroder,

Thank you for submitting your logbook of 3 images. I examined each image for the following criteria: sagittal section, angle of insonation angle less than 30 degrees, velocity more than 60 cm/s, and sample volume 2.0 mm (see table below).

	Image number		
Criteria	1	2	3
Sagittal section	-	~	>
Insonation angle < 30°	-	-	1
Velocity > 60 cm/s	×	4	>
Sample Volume 2.0 mm	-	-	1
Legend: ✓ = pass 🛛 🗡 = fail 🛛 = not possible to assess			

Your images are satisfactory. Your software license will include the assessment of **uterine artery flow** in the risk calculation for preeclampsia and your name will appear on the list of sonographers certified for assessment of uterine artery flow.

Best wishes,

Olga Torres Khoury